ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
8

Ward Name
Kodigehalli

Street ID
W0004, W0009, W0003, W0193, W0197, W0164, W0158, W

Street Name
NA, Vinayaka Lyt 2nd Crs, Vinayaka Lyt 1st Crs

Significant Landmark
Kodigehalli Village

Segment No.
8/C-W0004/S080641

Total Length (m)
297.72

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	77.88	77.573168	13.059980	77.573023	13.059291	W0014	SDW
2	91.94	77.572884	13.060038	77.572731	13.059220	W0197	SDW
3	31.44	77.573991	13.061142	77.574273	13.061074	W0009	RI-S64
4	96.46	77.574407	13.061471	77.574192	13.060625	W0034	M0006

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Cross Roads and Drain in Kodigehalli Village in ward no 8 Kodigehalli Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
1000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Cross Roads and Drain in Kodigehalli Village in ward no 8 Kodigehalli Sub-Division Yelahanka zone

Job No. / Work Code
008-15-000042

Work Order No.
EE/BTP/BBMP/E-PMT/WO/24/2015-16

Work Order Date
20/04/2015

Period of Extention
60 DAYS

Defect Liability Period From
20/10/2016

Defect Liability Period To
19/10/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
AMRUTHRAJ K

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
0.00

Phone No.

E-Mail ID

4726399

ield Inspection Details

umber of Trees	Any Other Information	Name
9		SRINIVASA MURTHY
Date of Inspection	**Remarks**	
16/01/2017	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0004, W0009, W0003, W0193,

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	16/01/2017	15/02/2017	COMPLETED
SE	VASU K M	16/01/2017	15/02/2017	COMPLETED
EE	MOHAN DAS HT	16/01/2017	15/02/2017	COMPLETED
AEE	RAJNIKANTH MALLI	16/01/2017	15/02/2017	COMPLETED
AE	SRINIVAS MURTHY	16/01/2017	15/02/2017	COMPLETED
AE	SRINIVAS MURTHY	16/01/2017	15/02/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0004, W0009, W0003, W0193,